


Static electricity on the film attracts the product which causes bad sealing on the top and bottom of the bags. This is a common problem with light and dusty products.

A 1250-S Bar here, just before the metal shoulder will neutralise the inside of the film / bag. The bar must be before the shoulder, not over it.



Filling Tube

Position 2 x 1250-S Static Eliminator Bars just below the filling tube - Important: it must be below the tube—and 20mm away from the film.

The 1250-S Bars should be just above the top position of the horizontal sealer.